D. And THIS PREVIOUS SHIPTONS	THE RESIDENCE TO A SERVE A COM	September 1 Marie 1 Land Land Company	WFC. 6-63 ROUTING
Approved For Release 2	003/12/23 : CIA-RDP66B00664F	400020044-7	6. 7 in section of an amplication and a section ( ) appropriate proof of 1973, 6. C.
TE .		2	80
	SECRET	3	11
2138Z Ø6 MAR 64	кылууды жын, тылгын кен жениликтү штуу тар отказатын татартында алат ойологу болгон жайын кайжататарган ай	4	12
Libergram and the sequence of	e of again dig - 1, mon programme merge analysis any managame any managament of the second of the second or an Of 1874, the second of the second or any communication of the second or any second or second or any second or secon	5	13
: DIRECTOR		6	16
25X1A	•	7	15
IOM :	*	B.	116   Marie de la companie
TION: 0PS 1-12	1	ROUTINE	
FO :		Amplica (1886 e esta micro) so oscilla tra-communication d	The second secon
TOR: 2353Z 6 MAR 64			IN 664125X1

25X1A

SUBJECT: FILM EVALUATION MISSION SØ74E.

- 1. CAMERA B 10 WAS USED IN MISSION S074E FLOWN ON 1 MARCH 1964;
  PROCESSING WAS ACCOMPLISHED BY 25X1A
  - 2. ORIGINAL NEGATIVE:
- A. THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS FAIR TO GOOD DUE TO ATMOSPHERIC CONDITIONS.
- B. 9R SIDE: THE FILM WAS RECEIVED AT THE PROCESSING SITE WITH INTERMITTENT MINOR CREASES AND SMALL TEARS ALONG BOTH EDGES POSSIBLY DUE TO THE FILM MISTRACKING. THIS DAMAGE IS LESS THAN THAT REPORTED ON MISSION 0064E. NUMEROUS SHORT PLUS DENSITY STREAKS OF VARIOUS LENGTHS AND LOCATED RANDOMLY ACROSS THE FORMAT ARE NOTICEABLE IN LOW DENSITY FRAMES. TWO ALTERNATING PLUS DENSITY STREAKS, PARALLEL TO THE FILM EDGES, ARE PRESENT 3.3" FROM THE OUTBOARD EDGE AND 3.25" FROM THE INBOARD EDGE OF THE FILM THROUGHOUT. A ROW OF MINUS DENSITY DOTS, SPACED 1.55" APART, ARE PRESENT 1.6" FROM THE AND PARALLEL TO THE OUTBOARD EDGE OF THE FILM THROUGHOUT. A WAVERING PLUS DENSITY STREAK, APPROXIMATELY 6.25" LONG, IS PRESENT IN FRAMES 1290

SECRET

CREMP 1 Included from automotic downgreding and declaration Approved For Release 2003/12/23: CIA-RDP66B00664R089400020044-7

25X1A

1935 (IN 66412) SECRET PAGE TWO

AND 1323. NANUFACTURER'S SPLICES ARE PRESENT IN FRAMES 2394 AND 2728.

- C. 9L SIDE: A WAVERING MINUS DENSITY STREAK OCCURS ALONG THE INBOARD EDGE OF THE FILM ON FRAME 801 TO THE MANUFACTURER'S SPLICE IN FRAME 805. TWO ROWS OF MINUS DENSITY DOTS, SPACED 1.55" APART. OCCUR 0.1" AND 3.2" FROM AND PARALLEL TO THE INBOARD EDGE OF THE FILM THROUGHOUT. MANUFACTURER'S SPLICES ARE PRESENT IN FRAMES 1983 AND 3152.
  - D. BOTH SIDES: FRAMES ARE TITLED 0000 THROUGH 3258.
- E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING FROBLEMS ENCOUNTERED DURING THIS MISSION.
  - 3. POSITIVE:
- A. PI SUITABILITY IS GOOD WHERE NOT DEGRADED BY CLOUDS AND HAZE.
  - B. PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 25 PERCENT OF THE MISSION.

END OF MESSAGE

SECRET